



WORLD HEADQUARTERS • BENTON HARBOR, MICHIGAN 49022-2692

This Class Code 91 letter is for module & motor assy. WPW10281342 (that contains only component W10281342) replacement for refrigerators. Due to a production change in the ice maker you will need to order a replacement according to your model number. Please refer to lists below.

For SERVICE KIT W10884390

596.72002011	596.72002013	596.72002015	596.72003012	596.72003014
596.72003016	596.72009011	596.72009013	596.72009015	596.72012012
596.72012014	596.72012016	596.72013012	596.72013013	596.72013014
596.72013015	596.72013017	596.72019012	596.72019014	596.72019016
596.79222011	596.79222012	596.79222013	596.79222014	596.79223011
596.79223012	596.79223013	596.79223014	596.79223015	596.79229011
596.79229012	596.79229013	596.79229014	596.79322011	596.79322013
596.79322015	596.79323012	596.79323014	596.79323016	596.79329011
596.79329013	596.79329015	596.79522013	596.79522014	596.79522015
596.79523014	596.79523015	596.79529013	596.79529014	596.79529015
596.79532014	596.79532016	596.79532018	596.79533015	596.79533017
596.79533019	596.79539014	596.79539016	596.79539018	AFD2535DEB10
AFD2535DEB11	AFD2535DEB9	AFD2535DEW1 0	AFD2535DEW1 1	AFD2535DEW9
AFD2535FES11	B22FT80SNS01	B22FT80SNS02	EB9SHKXVQ04	EB9SHKXVQ05
EB9SHKXVQ07	EF36BNNFSS11	EF36BNNFSS13	EF36BNNFSS9	GB2FHDXWB03

GB2FHDXWB04	GB2FHDXWB06	GB2FHDXWB07	GB2FHDXWQ03	GB2FHDXWQ04
GB2FHDXWQ06	GB2FHDXWQ07	GB2FHDXWQ08	GB2FHDXWS05	GB2FHDXWS06
GB2FHDXWS08	GB2FHDXWS09	GB9FHDXWB03	GB9FHDXWB04	GB9FHDXWB06
GB9FHDXWB07	GB9FHDXWQ03	GB9FHDXWQ04	GB9FHDXWQ06	GB9FHDXWQ07
GB9FHDXWS05	GB9FHDXWS06	GB9FHDXWS08	GB9FHDXWS09	GX2FHDXVB05
GX2FHDXVB06	GX2FHDXVB07	GX2FHDXVB08	GX2FHDXVQ04	GX2FHDXVQ05
GX2FHDXVQ06	GX2FHDXVQ07	GX2FHDXVY010	GX2FHDXVY07	GX2FHDXVY08
GX2FHDXVY09	GX5FHDXVB06	GX5FHDXVB07	GX5FHDXVB08	GX5FHDXVQ05
GX5FHDXVQ06	GX5FHDXVQ07	GX5FHDXVY010	GX5FHDXVY08	GX5FHDXVY09
GX5FHTXVB06	GX5FHTXVB07	GX5FHTXVB08	GX5FHTXVQ05	GX5FHTXVQ06
GX5FHTXVQ07	GX5FHTXVY010	GX5FHTXVY08	GX5FHTXVY09	IF36BNNFSF6
IF36BNNFSF8	IX3HHEXDMS00	IX5HHEXWS08	IX5HHEXWS09	IX5HHEXWS10
IX6HHEXDMS0		JFC2290VEM6		JFC2290VTB3
IX7HHEXDMS00		JFC2290VEM7		JFC2290VTB4
JFC2089BEM00		JFC2290VEM8		KBFS20ECBL00
JFC2089BEM01		JFC2290VEP6		KBFS20ECMS00
JFC2089BEP00		JFC2290VEP7		KBFS20ECWH00
JFC2089BEP01		JFC2290VEP8		KBFS20EVBL6
JFC2089WEM11		JFC2290VPF3		KBFS20EVBL8
JFC2089WEM7		JFC2290VPF4		KBFS20EVMS11
JFC2089WEM9		JFC2290VPF5		KBFS20EVMS13
JFC2089WEP11		JFC2290VPR2		KBFS20EVMS9
JFC2089WEP7		JFC2290VPR3		KBFS20EVWH6
JFC2089WEP9		JFC2290VPR4		KBFS20EVWH8
JFC2089WTB5		JFC2290VPY3		KBFS22ECBL00
JFC2089WTB7		JFC2290VPY4		KBFS22ECMS00
JFC2089WTB9		JFC2290VPY5		KBFS22ECWH00

KBFS22EWBL3	KRFF302ESS01	MFD2562VEB9
KBFS22EWBL5	KRFF302EWH00	MFD2562VEM11
KBFS22EWBL7	KRFF302EWH01	MFD2562VEM9
KBFS22EWMS5	MBF1953DEE00	MFD2562VEW6
KBFS22EWMS7	MBF1953DEH00	MFD2562VEW8
KBFS22EWMS9	MBF1953DEM00	MFF2258DEE00
KBFS22EWWH3	MBF1953YEB2	MFF2258DEE01
KBFS22EWWH5	MBF1953YEB4	MFF2258DEH00
KBFS22EWWH7	MBF1953YEW2	MFF2258DEH01
KBFS25ECBL00		MFF2258DEM00
KBFS25ECMS00	MBF1953YEW4	MFF2258DEM01
KBFS25ECWH00	MBF1958DEE00	MFF2258VEB5
KBFS25EWBL5	MBF1958DEH00	MFF2258VEB6
KBFS25EWBL7	MBF1958DEM00	MFF2258VEB7
KBFS25EWBL9	MBF1958XEB2	MFF2258VEB8
KBFS25EWMS10	MBF1958XEB3	MFF2258VEM7
KBFS25EWMS6	MBF1958XEB5	MFF2258VEM8
KBFS25EWMS8	MBF1958XEB6	MFF2258VEM9
KBFS25EWWH5	MBF1958XEQ2	MFF2258VEW4
KBFS25EWWH7	MBF1958XES2	MFF2258VEW5
KBFS25EWWH9	MBF1958XES3	MFF2258VEW6
KBRS20EVBL4	MBF1958XES5	MFF2258VEW7
KBRS20EVMS6	MBF1958XES6	MFF2558DEE00
KFCO22EVBL3	MBF1958XEW2	MFF2558DEH00
KFCO22EVBL4	MBF1958XEW3	MFF2558DEM00
KFCO22EVBL5	MBF1958XEW5	MFF2558VEB6
KFCP22EXMP3	MBF1958XEW6	MFF2558VEB7
KFCP22EXMP4	MBF2258DEE00	MFF2558VEB8
KFCP22EXMP5	MBF2258DEH00	MFF2558VEM9
KFCS22EVBL3	MBF2258DEM00	MFF2558VEW5
KFCS22EVBL4	MBF2258XEB3	MFF2558VEW7
KFCS22EVBL5	MBF2258XEB5	RDDFF236SS00
KFCS22EVMS6	MBF2258XEB6	RDDFF236SS02
KFCS22EVMS7	MBF2258XEW3	RDDFF236SS03
KFCS22EVWH3	MBF2258XEW5	RF36NDFSS000
	MBF2258XEW6	VCFF236SS000
KFCS22EVWH4	MBL2258XES3	VCFF236SS002
KFCS22EVWH5	MBL2258XES5	VCFF236SS003
KRFC300EBL00	MBL2258XES6	WRB322DMBB00
KRFC300EBL01	MBR1953YES2	WRB322DMBM00
KRFC300ESS00	MBR1953YES4	WRB322DMBW00
KRFC300ESS01	MBR2258XES3	WRF532SMBB00
KRFC300EWH00	MBR2258XES5	WRF532SMBB01
KRFC300EWH01	MBR2258XES6	WRF532SMBM00
KRFF302EBL00	MFC2061KES14	WRF532SMBM01
KRFF302EBL01	MFC2062DEM00	WRF532SMBW00
KRFF302ESS00	MFC2062DEM01	WRF532SMBW01

WRF535SMBB00	WRF540CWBB00	596.79422410
WRF535SMBM00	WRF540CWBB01	596.79423410
WRF535SMBW00	WRF540CWBM00	596.79422411
WRF535SWBB00	WRF540CWBM01	596.49423411
WRF535SWBM00	WRF540CWBW00	
WRF535SWBW00	WRF540CWBW01	

For Service KIT W10886931

B22CT80SNP01	B22CT80SNS01	JFC2290REM00	JFC2290REP00	JFC2290REY00
JFC2290RTB00	KRFC302EBL00	KRFC302EBS00	KRFC302ESS00	
KRFC302EWH00	RVTF3360SS00	WRF767SDEM01	WRV986FDEM01	

For Service Kit W10916040

ED5KVEXVB07	ED5KVEXVQ07	ED5PVEXWS14	ED5VHEXVB09
ED5VHEXVQ09			